

RFP, DACA87-02-R-001
Questions and Answers – Round 03

1. Paragraph 3.4.2 CQC Manger, Page 01451-4 Refers to a Graduate Engineer, Graduate Architect, or a Graduate of Construction Management – will a professional engineering license provide enough to qualify for this position as it relates to education?

ANSWER: The questioned paragraph in Section 01451 states that "The CQC System Manager shall be a graduate engineer, graduate architect, or a graduate of construction management, with a minimum of 8 years construction experience on construction similar to this contract." Qualification remains as stated.

2. Attachment 5 pg 7 for 3.03.3 IDT/DSCS Fac, Eareckson AS, BMC3 Facilities WBS 3.03.3.1.2 shows Mob/Demob Attachment 4 for 3.03.3 BMC3 Facilities WBS 3.03.3.1.3 shows Mob/Demob It would seem that 3.03.3.1.3 is correct.

Attachment 5 pg 7 for 3.03.3 IDT/DSCS Fac, Ft. Greely, AK, BMC3 Facilities WBS 3.03.3.8 shows Project Management Attachment 4 for 3.03.3 BMC3 Facilities WBS 3.03.3.9 shows Project Management. It would seem that 3.03.3.9 is correct.

Attachment 5 pg 7 for 3.03.3 IDT/DSCS Fac, Ft. Greely, AK, BMC3 Facilities WBS 3.03.3.9 shows Govt Suppt Activities Attachment 4 for 3.03.3 BMC3 Facilities WBS 3.03.3.10 shows Govt Suppt Activities. It would seem that 3.03.3.10 is correct.

Attachment 5 pg 7 for 3.03.3 IDT/DSCS Fac, Ft. Greely, AK, BMC3 Facilities WBS 3.03.3.10 shows Planning Attachment 4 for 3.03.3 BMC3 Facilities WBS 3.03.3.11 shows Planning. It would seem that 3.03.3.11 is correct.

Attachment 5 pg 7 for 3.03.3 IDT/DSCS Fac, Ft. Greely, AK, BMC3 Facilities WBS 3.03.3.12 shows Award Fee Attachment 4 for 3.03.3 BMC3 Facilities WBS 3.03.3.13 shows Award Fee. It would seem that 3.03.3.13 is correct.

Attachment 5 pg 7 for 3.03.3 IDT/DSCS Fac, Ft. Greely, AK, BMC3 Facilities WBS 3.03.3.13 shows Pass-Through Cost Attachment 4 for 3.03.3 BMC3 Facilities WBS 3.03.3.14 shows Pass-Through Cost. It would seem that 3.03.3.14 is correct.

ANSWER: Concurred. This section will be corrected with an Amendment to the RFP.

3. Does Subcontractor pricing need to accompany Sub Contractor Commitment letters?

ANSWER: The commitment letter instruction on subcontractors pertains to the management factor. See RFP, p. 34. The instructions on subcontract pricing pertain to the cost proposal, and are distinct from the letter of commitment. See RFP, p. 44.

4. In the Quantity Takeoffs and statement of work the solicitation refers to TYPE A, B and C fencing. In Section 02821 ASTM specifications, they also refer to Type A, B, and

C fence, but nowhere in the solicitation is a definition for Type A, B, and C. Can you please clarify this for me.

ANSWER: Fence types are shown on the drawings that will be furnished after award.

5. In Section 02821 3.3.1, 3.4.1, it refers to drawings. Where can these drawings be found, or is it assumed that the ASTM shop drawings are incorporated into the ASTM reference?

ANSWER: Fence types are shown on the drawings that will be furnished after award.

6. There appear to be contradictions in the ASTM specifications in Section 02821 and the materials designated in the solicitation and Quantity Take-offs, i.e. By reference, ASTM specifications for 8 foot fence do not specify 2" line posts, which is what is described in Section 9.3.7.2, page 421 of the solicitation. This is a direct contradiction of acceptable industry standard. How should we bid this?

ANSWER: Page 411 – paragraph 9.3.5.2.1, describes the fence materials and resolves any inconsistency.

7. On page 421 of the solicitation, section 9.3.7.1 refers to Figure 1. Where can this be located?

ANSWER: See page 292.

8. In the RFP, page 83 of 462 is missing. This is the 'Reps and Certs' signature page. Please send the signature page.

ANSWER: Page 83 of the RFP was omitted, and will not be included. Section 00600 must be completed and the offeror must sign on page 2, Block 20B.

9. In the RFP, Amendment 2, please verify the unit 'MLF' or the numerical value in the Material Takeoff attachment for the Missile Assemble Bldg (WBS 9.1.2) for the fire alarm system item (alarm & communication cable, #14, 1 pair, in conduit) with a quantity of 1725. This also applies to fire alarm system on WBS 9.2.2 (Oxidizer storage), WBS 9.2.1 (EKV Fuel storage), and WBS 9.2.5 (Utilities Bldg) .

10. **ANSWER:** MLF is a Unit of Measure (UOM) for thousand linear feet. The UOM is "MLF", however the quantity for the fire alarm system for alarm & communication cable, #14, 1 pair is changed from 1725 to 1.725 for those WBS identified.